

# EYE WASH TESTING

DATE 3/10/15

BIOCHEM LABS		UNIT #	✓	5TH FLOOR		UNIT #	✓	3RD FLOOR		UNIT #	✓
SUB BASEMENT				5TH FLOOR				3RD FLOOR			
B248	1			563	35			3206	63		
B242	2			563	36			3270	64		
BASEMENT				557	37			3268	65		
B175	3			545	38			<u>3265</u>	66		
1ST FLOOR				545	39			3266	67		
161	4			580	40			<u>3241</u>	68		
145	5			BSB 85 WING				2ND FLOOR			
145	6			6TH FLOOR				2228	69		
123	7			6424A	41			2222	70		
123	8			6420B	42			2212	71		
123	9			6412A	43			2210	72		
2ND FLOOR				6406A	44			2206	73		
265	10			4TH FLOOR				2267	74		
259	11			4424	45			2265	75		
255	12			4416B	46			2268	76		
249	13			4416A	47			2264	77		
245	14			4406A	48			2241	78		
237	15			3RD FLOOR				<p>Has loose panel, the bottom one that cause drain pipe</p>			
233	16			3416	49						
219	17			2ND FLOOR							
207	18			2424A	50						
275	19			2416A	51						
3RD FLOOR				2410	52						
363	20			2406	53						
345	21			1ST FLOOR							
337	22			1404	54						
333	23			BSB							
319	24			BASEMENT							
307	25			B2422	55						
379	26			B2423	56						
373	27			B2409	57						
4TH FLOOR				3RD FLOOR							
461	28			3228	58						
457	29			3222	59						
445	30			3212	60						
435	31			3210	61						
419	32			3211	62						
407	33										
473	34										